

[Next Unread Message](#)**View Message****Sent on** 10 30 2013 **Expires on** 11 12 2013**From** Parts and Service Division**Subject** Request for Info: 2007-2008 Fit Water Leak

To: All Honda Service Managers/Advisors  
From: Technical Research & Support Group  
RE: Request for Info: 2007-2008 Fit Water Leak

Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2007-2008 Fits with a complaint of water leak inside the cabin. To fully understand the cause of this condition, AHM would like to collect specific information from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Confirm that this issue is NOT related to the Service Bulletin 08-033 2007-2008 Fit Rear Washer Nozzle Broken or Missing.
2. Click [here](#) to answer a short questionnaire to describe the water leak.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.